SITE PHOTOGRAPHS



Figure 1: Vegetation on site




Figure 2: Animals on site




Figure 3: Existing Road D5010 on the village side (Nkotokwane)




Figure 4: Proposed new Road D5021 across the Olifants River




Figure 5: Olifants River





Figure 6: Waste dumping observed on site






Figure 7: Showing the community crossing the river.